

RECEIVING INSPECTION REPORT  
 Approved For Release 2009/04/18 : CIA-RDP81B00879R000500080060-7  
 No. 11872

RECEIVED FROM

DATE REC'D. 4-11-57

P.O. NO.

VENDOR PACKING SLIP NO.

CONTRACT  
CODE NO.

DRAWING  
NUMBER

DWG. DASH OR  
STANDARD PART NO.

DWG.  
REV.

LOT  
NO.

CLASS  
NUMBER

OPER.  
NUMBER

BUY OUT  
CODE NO.

O  
R

ACCT. OR  
W.O. NO.

S.O. NO.

CHANGE TO  
QUANTITY  
RECEIVED

DRAWING NO. AND DESCRIPTION

QUANTITY

ACCEPTED

REJECTED

REMARKS

730109-9 Capacitor .1 MFD - 200V

20

*Ston*

REF #5357

*W.E. Parker*  
*W.E. Parker*

RECEIVED BY *Barcellos*

INSPECTED BY

*KPE*

DATE 4-11-57

REJECTS RETURNED  
ON SHIP MEMO NO.

RECEIVING INSPECTION REPORT

HYCON MFG. COMPANY

2351 E. COLORADO ST., PASADENA, CALIF.

No. 11874

RECEIVED FROM

DATE REC'D. 4-11-57

P.O. NO.

VENDOR PACKING SLIP NO.

CONTRACT  
CODE NO.

DRAWING  
NUMBER

DWG. DASH OR  
STANDARD PART NO.

DWG.  
REV.

LOT  
NO.

CLASS  
NUMBER

OPER.  
NUMBER

BUY OUT  
CODE NO.

O  
R

ACCT. OR  
W.O. NO.

S.O. NO.

CHANGE TO  
QUANTITY  
RECEIVED

DRAWING NO. AND DESCRIPTION

QUANTITY

ACCEPTED

REJECTED

REMARKS

150

739829 Data Card

150

*38*

REF #5356

*W.E. Parker*  
*W.E. Parker*

RECEIVED BY *Barcellos*

INSPECTED BY

*KPE*

DATE 4-11-57

REJECTS RETURNED  
ON SHIP MEMO NO.